

Precision digital pressure gauge DIM 30

Ordering data

DG: H, PG: 4

Digital local display and evaluation software

33406 Display unit DIM 30 with evaluation software (CD-ROM) and PC connection cable (USB)

1 Pressure sensor, pressure type

- R** Relative
- A** Absolute (possible for 0.4 bar and higher)

2 Measuring range in bar

- 100** -1/0
- 102** -1/+1.5
- 103** -1/+3
- 104** -1/+5
- 007** 0/0.10
- 008** 0/0.16
- 009** 0/0.25
- 010** 0/0.40
- 108** 0/0.60
- 109** 0/1.0
- 110** 0/1.6
- 111** 0/2.5
- 112** 0/4.0
- 113** 0/6.0
- 114** 0/10
- 115** 0/16
- 116** 0/25
- 117** 0/40
- 118** 0/60
- 119** 0/100
- 120** 0/160
- 121** 0/250
- 122** 0/400

3 Process connection

- 01** G ½ (DIN 3852)
- 02** G ½B (EN 837-1)
- 03** G ¼ (DIN 3852)
- 04** G ¼B (EN 837-1)
- 05** ½-14 NPT
- 06** ¼-18 NPT

4 Seal

- 0** Without seal (only process connection as per EN 837-1)
- 1** FKM
- 9** Others

Ordering code

Example: 0/10 bar, G½B

Pressure sensor DIM 30	R	114	02	0
---------------------------	---	-----	----	---